



## Problem Statement

- Account for all missing miners
- Explore all areas that can be done so safely
- Leave the mine so recovery work can be done barefaced
- Report the condition and location of all seals encountered
- Air must remain coursing in all entries during the working of the problem

# Practice Problem #2




# Practice Problem #2




**1st Ventilation**

# Practice Problem #2



## 2nd Ventilation



Team Stops